




TIMING BELT KITS

PA0018 - T1234

To ensure long-term performance and reliability, FAI recommends replacing the hydraulic damper each time the timing belt or kit is renewed.

Failing to replace the damper may lead to inconsistent belt tension, causing the belt to operate outside its specified tolerances. This can increase noise during operation and potentially reduce the overall lifespan of the components.

T1234



TBK85



| Make | Model | Year | Engine Size |
|---------|--------|-------------------|-------------------|
| CITROËN | RELAY | 01/1999 - 02/2002 | 2.8 D |
| FIAT | DUCATO | 07/1990 - 03/2002 | 2.5/2.8 TD |
| IVECO | DAILY | 01/1985 - 07/2007 | 2.5/2.8 TD |
| PEUGEOT | BOXER | 01/1999 - 02/2002 | 2.8 D |
| RENAULT | MASTER | 08/1989 - 07/1998 | 2.5 TD |