



PRODUCT AWARENESS


PA0045 -LR350 | CAMSHAFT CARRIER

Application: BMW & MINI 2.0D N47 Variants

A common occurrence in the BMW N47 engine variants is Timing Chain Kit failure.

When this occurs, the Camshaft Carrier has a tendency to fracture in one corner making it a popular replacement component.

Our LR350 includes all cam caps, cam cap bolts and O-Rings.



Manufacturer	Model Details	Engine	Dates	Engine Code	OE Reference
Alpina	D3	2.0D	2008 - 2013	N47D20D	
BMW	1 - 7 Series X1 X3 X5 X6	2.0D	2007 - 2016	N47 D20 A N47 D20 B N47 D20 C N47 D20 D	
MINI	CLUBMAN COOPER COUNTRYMAN PACEMAN ROADSTER	1.6/2.0 D	2009 -2016	N47 C20 A N47 C16 A	11317797511
TOYOTA	AURIS AVENSIS RAV4 VERSO	1.6/2.0D	2013-2018	1WW/2WW	

For more information, email technical@faiauto.com

faiauto.com

