




CAMSHAFT CARRIER

PA0070 - LR340

Applications: Ford 3.2 TCDi

The ladder rack on this engine is prone to damage due to timing chain failure aswell as general wear and tear.

If a replacement is needed due to timing failure(s), the engine valves must be checked for damage and replaced if needed.



Manufacturer	Model	Engine	Dates	Engine code	OE Reference
FORD	RANGER	3.2 TDCi 4x4	2011 >	ENSA SA2R	1756384
	TRANSIT	3.2 TDCi RWD	2007 - 2014	SA2S SA2W	BK3Q-6K551-BC
	TRANSIT	3.2 TDCi	2008 - 2014	SAFA SAFB	